

AUTOHISTORIC LTD

Unit 2 Willow Farm, Scrapers Hill Chiddingly, East Sussex, BN8 6HJ United Kingdom

Telephone: 01825873636 Email gregg@autohistoric.co.uk

Invoice To: SALES INVOICE

Mr Adrian Beal Flat 1, Bolsover Court 19, Bolsover Road Eastbourne East Sussex BN20 7JG

Invoice DateReferenceInvoice Number02/08/2024E-type Series 3 DHCSI-1283

LA1 Work list as follows: 8.50 70.00 2	20.00 59	95.00
LAT Work list as follows.		90.00
Address brake hang issues - particularly evident when hot. - Thoroughly check hydraulic and vacuum systems - Vacuum test all lines and solid pipework - Strip and inspect multiple master cylinder and reaction valve assemblies to determine cause of fault. - Carry out machining work to reaction valve to improve clearances and surface finish. - Reassemble, bleed hydraulics and test. Rectify aerial stuck in the raised position		
Replace cooling fan relay with modern unit - original left in place but disconnected		
Carry out approximately 60 miles total road testing		
Brake fluid - DOT4 1.50 19.29 2	20.00 2	28.94
FUEL1 Fuel - High octane 38.00 1.47 2	20.00	55.86

VAT Rate	Net	VAT	Total Net	679.80
Standard 20.00% (20.00%)	£679.80	£135.96	Total VAT	135.96
			TOTAL	£815.76

Notes:

Bank Details: Autohistoric Ltd Lloyds Bank Account: 53615168 Sort: 30-97-66

IBAN: GB13 LOYD 3097 6653 6151 68

BIC: LOYDGB21140



Terms and Conditions:

Payment due on receipt of invoice.

AUTOHISTORIC LTD

Unit 2 Willow Farm, Scrapers Hill Chiddingly, East Sussex, BN8 6HJ United Kingdom

Telephone: 01825873636 Email gregg@autohistoric.co.uk